





KUSTOS BT B 25		A mm									
		100	110	120	130	140	150	160	170	180	190
B mm	100	103°	108°	112°	116°	119°	110°	104°	99°	96°	93°
	110	102°	106°	110°	114°	111°	105°	99°	96°	92°	
	120	101°	105°	109°	112°	106°	100°	96°	92°		
	130	100°	104°	108°	109°	101°	96°	92°			
	140	99°	103°	106°	102°	96°	92°				
	150	99°	103°	102°	96°	92°					
	160	99°	102°	96°	93°						
	170	98°	98°	91°							
	180	91°	92°								
	190	91°									
	200										
	210										

A ≈ B 👍

α°