





KUSTOS BT B 40

A mm

		100	110	120	130	140	150	160	170	180	190	200	210	220
B mm	100	103°	108°	112°	115°	118°	121°	124°	122°	114°	109°	104°	101°	98°
	110	102°	106°	110°	113°	117°	120°	123°	116°	110°	105°	101°	98°	95°
	120	101°	105°	109°	112°	115°	118°	121°	112°	106°	102°	98°	95°	
	130	101°	104°	108°	111°	114°	117°	114°	107°	102°	98°	95°		
	140	100°	103°	107°	110°	113°	116°	108°	103°	99°	95°			
	150	99°	102°	106°	109°	112°	114°	104°	99°	95°				
	160	98°	102°	105°	108°	110°	105°	99°	95°					
	170	98°	101°	104°	107°	107°	100°	95°						
	180	98°	101°	103°	106°	100°	95°							
	190	97°	100°	102°	105°	95°								
	200	97°	100°	101°	95°									
	210	96°	99°	97°										
	220	96°												

A ≈ B 👍

α°